

## Suverehvid 2018/2019

Mõõt	Tootja	Mudel	Hind	Soodushind
<b>165/70R14</b>	<i>Continental</i>	ContiPremContact 5	85	<b>64</b>
<i>UP!</i>	<i>Barum</i>	Brillantis 2	65	<b>49</b>
<b>175/65R14</b>	<i>Continental</i>	ContiPremContact 5	85	<b>64</b>
<i>Polo, UP! Caddy -03</i>	<i>Barum</i>	Brillantis 2	65	<b>49</b>
<b>175/70R14</b>	<i>Continental</i>	ContiEcoContact 5	105	<b>79</b>
<i>Polo 10-</i>	<i>Barum</i>	Brillantis 2	75	<b>56</b>
<b>185/65R15</b>	<i>Continental</i>	ContiEcoContact 5	95	<b>71</b>
<i>Polo 2017-</i>	<i>Barum</i>	Barum Brillantis 2	75	<b>56</b>
<b>195/65R15</b>	<i>Continental</i>	ContiPremContact 5	115	<b>86</b>
<i>Passat, Golf, Caddy, Touran</i>	<i>Barum</i>	Brillantis 2	75	<b>56</b>
	<i>Barum</i>	Brillantis 2 XL (Caddy)	90	<b>68</b>
<b>195/60R16C</b>	<i>Continental</i>	VanCont 100	190	<b>143</b>
<i>Sharan 2001-2010</i>	<i>Barum</i>	Vanis	130	<b>98</b>
<b>205/55R16</b>	<i>Continental</i>	ContiPremContact 5	120	<b>90</b>
<i>Golf, Passat, Jetta, Touran</i>	<i>Barum</i>	Bravuris 3 HM	95	<b>71</b>
<b>205/60R16</b>	<i>Continental</i>	ContiPremContact 5	155	<b>116</b>
<i>Touran 2015-</i>	<i>Barum</i>	Bravuris 2	110	<b>83</b>
<b>215/55R16</b>	<i>Continental</i>	ContiPremContact 5	200	<b>150</b>
<i>Passat, Sharan 2001-2010</i>	<i>Barum</i>	Bravuris 3 HM	135	<b>101</b>
<b>215/60R16</b>	<i>Continental</i>	ContiPremContact 5	200	<b>150</b>
<i>Passat 2015-, Sharan 2011-</i>	<i>Barum</i>	Bravuris 2	135	<b>101</b>
<b>215/65R16</b>	<i>Continental</i>	ContiPremContact 5	165	<b>124</b>
<i>Tiguan</i>	<i>Barum</i>	Bravuris 4x4	125	<b>94</b>
<b>215/55R17</b>	<i>Continental</i>	ContiPremContact 5	240	<b>180</b>
<i>Passat 2015-, Touran 2015-</i>	<i>Barum</i>	Bravuris 3 HM	140	<b>105</b>
<b>225/45R17</b>	<i>Continental</i>	ContiPremContact 6 FR	175	<b>131</b>
<i>Golf 7</i>	<i>Barum</i>	Barum Bravuris 3 HM FR	120	<b>90</b>
<b>225/50R17</b>	<i>Continental</i>	ContiPremContact 6 FR	230	<b>173</b>
<i>Passat Alltrack</i>	<i>Barum</i>	Bravuris 3 HM FR	140	<b>105</b>
<b>225/55R17</b>	<i>Continental</i>	ContiPremContact 5 FR	235	<b>176</b>
<i>Passat Alltrack 2015-, Arteon</i>	<i>Barum</i>	Barum Bravuris 3 HM FR	145	<b>109</b>
<b>235/45R17</b>	<i>Continental</i>	ContiPremContact 6 FR	195	<b>146</b>
<i>Passat, Passat CC, EOS, Scirocco</i>	<i>Barum</i>	Bravuris 3 HM FR	130	<b>98</b>
<b>225/65R17</b>	<i>Continental</i>	ContiCrossContact LX 2 FR	215	<b>161</b>
<i>Tiguan 2016-</i>	<i>Barum</i>	Bravuris 4x4 FR	160	<b>120</b>
<b>235/55R18</b>	<i>Continental</i>	ContiPremiumCont 6 SUV	250	<b>188</b>
<i>Tiguan 2016-</i>				
<b>215/50R18</b>	<i>Continental</i>	ContiSportContact 5 FR	275	<b>206</b>
<i>T-Roc</i>				
<b>245/70R16</b>	<i>Continental</i>	ContiCrossCont LX 2 FR	195	<b>146</b>
<i>Amarok</i>	<i>Barum</i>	Bravuris 4x4	155	<b>116</b>
<b>255/60R18</b>	<i>Continental</i>	ContiCrossContact LX 2	245	<b>184</b>
<i>Amarok</i>				
<b>255/55R19</b>	<i>Continental</i>	ContiPremiumContact 6 FR	275	<b>206</b>
<i>Amarok</i>	<i>Barum</i>	Barum Bravuris 3 HM	215	<b>161</b>
<b>235/65R17</b>	<i>Continental</i>	ContiCrossContact LX 2 FR	220	<b>165</b>
<i>Touareg</i>	<i>Barum</i>	Bravuris 4x4 FR	165	<b>124</b>
<b>255/55R18</b>	<i>Continental</i>	ContiCrossCont LX 2 FR	255	<b>191</b>
<i>Touareg</i>	<i>Barum</i>	Bravuris 4x4 FR	175	<b>131</b>
<b>205/65R16C</b>	<i>Continental</i>	VancoContact 200	210	<b>158</b>
<i>Transporter T5, T6</i>	<i>Barum</i>	Vanis 2	145	<b>109</b>
<b>215/65R16C</b>	<i>Continental</i>	VancoContact 200	215	<b>161</b>
<i>Transporter T5, T6</i>	<i>Barum</i>	Vanis 2	150	<b>113</b>
<b>235/55R17</b>	<i>Continental</i>	ContiPremContact 5	240	<b>180</b>
<i>Multivan</i>	<i>Barum</i>	Barum Bravuris 3 HM FR	185	<b>139</b>
<b>205/75R16C</b>	<i>Continental</i>	VancoContact 200	220	<b>165</b>
<i>Crafter</i>	<i>Barum</i>	Vanis 2	145	<b>109</b>
<b>235/65R16C</b>	<i>Continental</i>	VancoContact 200	260	<b>195</b>
<i>Crafter</i>	<i>Barum</i>	Vanis 2	180	<b>135</b>